Press the Zero Emission button on the Multifunction Control Panel (Figure 22).




Figure 24

Select CARWINGS) and then CARWINGS Settings.




Figure 25

3. Select Sign in.




Figure 26